

APPLICATION No.: 24651

TAP CLEARED

LOCATION: 399 John St.

OWNER: Joseph A. Perreira

MEASURES: 1" Copper Dec. 11, 1956

N from N line      Westbrook St.      104.3 ft.

E from W line      John St.      7.9 ft.

N from S line      house      4.4 ft.

✓ Jan. 4, 1957 Repaired service by installing a 8" x 1"  
DC-20-7E Smith-Blair Saddle

© 2009 Blackwell Publishing Ltd

✓ July 22, 1992 poor pressure - change saddle.  
✓ Renewed from main to a point 1½ ft. from main.

Stock:

1½ ft. - 1" copper tubing 1 - 1" x 1" cop to cop cplg., comp.

1" corp. tap                      8" x 1" Adams Servi Seal Clamp

BRADBURY-WARING, INC.

[illegible]

## CHARGE OUTS