
to proper	#1409 APPLICATION No.: 25804			TAP CLEARED			
LOCATION:	1399 Cove Rd		DATE	BEF.	AFT.	REMARKS	
OWNER:	116						
31-313 MEASURES:	Contractor: Araujo Brothers Plumbing	5.	-24-10	8:00		2010-2200 384	
	2" Copper 08-10-1960						
from aband \$70 Inspe Note: 2" c City crew Inspected 5/24/10 -	urb stop valve broke in "on" position - to repair by Percy Reynolds City crew renewed service from 1/2 ft o	ed					
1.5 ft - 2 stop box;	to 1.5 feet inside 2" copper tubing; 1 -2" curb stop; 1 Caldwell 1 -2" x 2" cop to cop cplg comp Danny Perry	dwell					
7/22/10-	Arawjo Brothers - picked up I" coupli reducing from 2" to 1" in side celled	np.					



APPLICATION No.: 25804 2" Copper		TAP	CLEAR	ED
LOCATION: No.: 2500# 2 Copper Location: Location: Location Rd. E x Orchard St.	DATE	BEF.	AFT.	REMARKS
OWNER: John Bodzrock				
MEASURES: 2" Copper Aug. 10,1960 1-2" Dar. All bell gate valve 0-ring; 1 R-144 Caldwell valve hox W from 1st hyd x Orchard 75.1 ft. S from N line Cove Rd. 6.2 ft. E from W line Bldg. 2.2 ft. Main is 16.2 ft. S x N line. Aug. 15, 1960 Service was extended from a point 1.8' inside proline to meter inside building 39' of 2" copper tubing 1/12/2010 Ed Vieira + Sons killed this service just vaside the property line - Inspected by Percy Reynolds.				

DATE SET OUT SIZE MAKE NUMBER READING TEST REMARKS 5/2/68 2" Calmet 1661826	GE CUTS
5/2/68 2" Calmet 1661826	
5/2/68 2" Calmet 1551825	