| \$ 592 APPLICATION No.: 25840 | TAP CLEARED | | | |
|--|-------------|---------|---------|------------|
| LOCATION: E.S. 600 Pleasant Stt.S x William St. | DATE | BEF. | AFT. | REMARKS V |
| OWNER: Franciscan Fathers | | | 11-9-95 | 9545-04571 |
| | 1.0 ft. | | | Has Elect. |
| October 5, 1967 Hole was dug around box, that just had to be turned. It was facing wrong way. Contractor resurfacing street will maintain all cuts. Nov. 9, 1995 The 3" gate valve was broken by overturning valve spection of gate & valve & replaced top section only. To be replaced new gasket 8 - 3" x ½" bolts & nuts March 22, 1996 Replaced broken valve. 3 ft 3" Copper tubing 1 - 3" Gate Valve, All Bell 2 - 3" Smith Blair #226 clar Measure of new valve: E x W line Pleasant St. 31.0 ft. | at a lat | ter dat | e. | |
| | | | | |

| METER HISTORY | | | | | | | | | | CHARGE OUTS |
|---------------|-----|------|------------|-------------|---------|--|------|--|---------|-------------|
| DATE | SET | SIZE | MAKE | NUMBER | READING | | TEST | | REMARKS | |
| 2-15-6 | 0 | 3" | Artic Trop | ie 17178820 | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| in the second | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | 1 | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

12-15-60