

APPLICATION No.: 26064

TAP CLEARED

LOCATION: N.W. Cor. Phillips 1315[#] Rd. & Maxine St.OWNER: Frank G. King132~~e~~/L19

MEASURES: 3/4"

	Copper	11-15-61
N from N line	Phillips Rd. East	1079.7 ft.
N from Ser. # 26063		160.5 ft.
E from W line	Phillips Rd.	6.2 ft.
N from N line	House	2.9 ft.

February 5, 1963 Repaired a 3/4" copper service which was broken by
the D.P.W. equipment while digging a drain trench.

Repaired broken service inside the property.

4 ft. of 3/4" copper tubing 2 3/4" cop. to cop. cplg. A-1525

DATE

BEF.

AFT.

REMARKS



[illegible]

CHARGE OUTS

[illegible]