

APPLICATION No.: 27802

## TAP CLEARED

LOCATION: S.S. 332 Natick St., W x Wildwood Rd.

DATE

BEF.

AFT.

REMARKS

OWNER: A. Hortin

## MEASURES:

1"

Copper

10-9-68

W from W line

Wildwood Rd.

228.0 ft.

N from S line

Natick St.

6.9 ft.

W from E line

House

7.2 ft.

N from N line

House

21.8 ft.

Main is 14 ft. N x S line.

September 30, 1970 Due to fact that the service saddle was broken it was necessary to install Smith Blair #331 repair sleeve.

2½ ft. - 1" copper tubing 1-1" coupling (2½' south from tap)

1 - Smith Blair repair sleeve 6"

- - -

October 6, 1970 Lowered Service

9 ft. - 1" Copper tubing

- - -

4/26/12 - City crew exposed & raised curb stop box

Jarred Medeiros

-----

[illegible]

## CHARGE OUTS