

APPLICATION No.: 29174

TAP CLEARED

LOCATION: E.S.4122 ACUSHNET AVE S X MANILLA ST

OWNER: ERNEST F LUPANIER

MEASURES: 1" COPPER JUNE 19 1974

S FROM S LINE MANILLA ST	106.7 ft
W FROM E LINE ACUSHNET AVE	3.5
S FROM N LINE HOUSE	13.7
W FROM W LINE HOUSE	45.2

MAIN IS 41 ft W X E LINE

Oct. 31, 1996: POOR PRESSURE 1" tap reamed
W Hansen & crew

6/5/08 - NE Pressure Project - City tied service into new 12"
main. Renewed from main to a point 5 ft
5 ft - 1: copper tubing; 1 - 1" x 1" cop to cop cplg. comp.
Foreman: Frank Bento

DATE

BEF.

AFT.

REMARKS

METER HISTORY

[illegible]

CHARGE OUTS

APPLICATION No.: 29174

TAP CLEARED 8523-1686

LOCATION: E.S. Acushnet Ave. S x Manilla St.

OWNER: Ernest F. Lupanier

MEASURES: 1" Copper June 19, 1974

S from S line Manilla St. 106.7 ft.

W from E line Acush. Ave. 3.5 ft.

S from N line House 13.7 ft.

W x W line House 45.2 ft.

Main is 41 ft. W x E line.

April 2, 1975 Repaired leak at tap - caused by settling of sewer trench.

Fontani will maintain trench.

6/18/81 Mello & hunt check this service for low pressure
Mello said he pumped it & got enough pressure for the
homeowner to be satisfied.

Mello & J. Duarte 11/12/81

June 20, 1985 Very poor pressure - Tap was plugged -
Reamed tap - Pressure very good now. Cut in 1" copper
to copper cplg., comp. - 1 ft. from tap.
1 - 1" x 1" cop to cop cplg., comp.

10/28/92: tap reamed NOTE: outside pressure from faucet is better than
pressure inside house. tap was made up tap reamed used same
1ft piece of copper & cop-cop cplg. from previous job

METER HISTORY

[illegible]

CHARGE OUTS