

124

APPLICATION No.: 29660

TAP CLEARED ✓

LOCATION: S.S. Maple St. W x Park St.

OWNER: Singer Heating Co.

MEASURES: 4" Ductile Pipe July 13, 1978

W from W line Park St. 73.0 ft.

N from S line Maple St. 12.0 ft.

F S  
I U  
R P  
E P  
L  
Y

Feb. 21, 1995 Repaired crack around 4" cast iron pipe approx. 7 ft.  
N x S line Maple St. Note: this service is cast iron not ductile iron pipe  
1 - 4" Smith Blair #226 full circle clamp cplg. 4.74 -5.14 OD 7½"W

-----

DATE

BEF.

AFT.

REMARKS

[illegible]