

APPLICATION No.: 31188

TAP CLEARED

LOCATION: 87 ROWE ST (W,S,JULIE PLACE N X POTTER ST)

OWNER: GILBERT H MACKIN

MEASURES: 1" copper tubing Jan.27,1989

N x N line Potter ST. 305.0ft

E x W line Rowe St 7.0ft

N x S line house 37.0ft

S x N line house 2.0ft

E x E line house 30.0ft

Main is 14ft E x W line

June 24,1996:

Service was leaking from repair made 6/12/96 by water dept.

Removed piece with kink in it ~~from clippers~~ Removed curb stop

Installed 4ft-1" copper (2) 1"x1" cop-cop cplg.comp

1 from 6/12/96 repair job.

Stock: 4ft 1" copper tubing 1-1"x1" cop-cop cplg.comp.

=====

DATE

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]

87 Rowe St.

APPLICATION No.: 31188

TAP CLEARED

LOCATION: W.S. Julie Pl. N x Potter S t.

DATE

BEF.

AFT.

REMARKS

OWNER:

Gilbert H. Mackin

31-313

MEASURES:

1"

Copper tubing

Jan. 27, 1989

N x N line Potter St.

305.0 ft.

E x W line Rowe S t.

7.0 ft.

N x S line house

37.0 ft.

S x N line house

2.0 ft.

E x E line house

30.0 ft.

Main is 14 ft. E x W line.

OVER FOR TIES

OCT. 18, 1994

*This serv. to be shut off before Main is
shut down. AIR IN SERVICE LINE*

June 12, 1996: Service was pulled while digging for sewer pipe
by contractor Repair made 12.9 W x water main

Stock: 4.0ft 1" copper tubing by contractor

1-1"x1" cop-cop cplg.comp by contractor

1-1" curb stop by water dept.

W.Hansen

CHARGE OUTS

DATE	SET-OUT	SIZE	MAKE	NUMBER	READING	TEST	REMARKS
			REC. 140				
<p>201.01</p> <p>N 33° - 52' - 00" E</p> <p>131.11'</p>				<p>LOT 7</p> <p>51127 s f</p>		<p>15'</p> <p>17.81'</p> <p>46.7</p> <p>264.85'</p> <p>S 26° - 54' - 05" E</p>	
<p>131.80'</p> <p>S 64° - 49' - 39" W</p> <p>n/f</p> <p>Marie B. Larrivee</p>				<p>40</p> <p># 31188</p> <p>24</p> <p>50</p>		<p>8.22</p>	
<p>JOHN HICKINSON</p> <p>REGISTERED</p> <p>PROFESSIONAL LAND SURVEYOR STATE OF MASSACHUSETTS</p> <p>NO. 14832</p>				<p>Potter St.</p>			

