89 Susan St.

| | | TAP CLEARED | | | | | | |
|-------------------------|--|------------------|--|------------------|------|------|------|---------|
| LOCATION:_ | S.S. St | usan St. North E | DN No.: 31211 E x Braley Rd. | | DATE | BEF. | AFT. | REMARKS |
| OWNER: _ | Braley | Farms Assoc. | LOT 1 | 62 | | | | |
| MEASURES: | | copper tubing | Turn on May 26, 1 Measures taken Ap | 1989 oril 15, | 1993 | | | |
| N x S E x W W x E | usan St. bound line Susan St. line house line house line house | (N) | 130.0 ft 4.2 ft 39.4 ft 5.2 ft 29.2 ft | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | , - | | | | |

| METER HISTORY | | | | | | | | | |
|---------------|-----|------|--|---------------------|---------|--|------|--|---|
| DATE | SET | SIZE | MAKE | NUMBER | READING | | TEST | | REMARKS |
| | | | 1- | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | 200 St. 100 St | - the second second | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | - | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

CHARGE OUTS