

33466

APPLICATION No.:

TAP CLEARED

LOCATION: 94 Front St

DATE

BEF.

AFT.

REMARKS

OWNER: NB Vision Realty LLC Contractor: Dyer Construction

31-313

MEASURES: 2" Copper 6/17/08 (2008)

S from S line Centre St 79.5

S from Hydrant 54.5

E from W line 4.0

N from N line Building 2.5

E from E line Building 4.0

Main to Property Line 22.0

Pipe inside property 5.0

[illegible]

## CHARGE OUTS

[illegible]



APPLICATION No.: 12711

TAP CLEARED ✓

LOCATION: 94 Front

OWNER: Rladores &amp; Manly

MEASURES:

 $\frac{1}{2}$ "

N from	Union	120.6
E from W line	Front	--7.0 3.4
S from N line	Bldg.	12.4
E from E line	Bldg.	3.4

Aug. 1, 1973 Renewed from main to 1 ft. inside curb stop. Due to South Terminal Work this service was relocated from the old main to the new main.

17 ft. - 3/4" Copper tubing 3/4" Hays curb stop  
3/4" Hays Corporation 1 wipe joint

11/8/77: Cut in new 3/4" curbstop and renewed into cellar. 10 ft.-  
3/4" copper (5 ft. ins.); 3/4" curb stop; Caldwell stop box;

Dec. 26, 1980 Thaw out service frozen - went there twice.

INACTIVE

REPLACED

BY 33466 - 204

[illegible]

## CHARGE OUTS

[illegible]