| × | 36 Bismark Meadoes Rd (ss) - 340' E x Bismark St (lot 515) | TAP CLEARED | | | |
|------------|--|-------------|------|------|---------|
| LOCATION:_ | | DATE | BEF. | AFT. | REMARKS |
| OWNER: | Ana Reis, Trustee Contractor: W.C. Smith & Son | | | | |
| MEASURES: | 1" Copper 05-29-2009 | | | | |
| | E from E line Bismark St 136.0 E from Hydrant 136.0 N from S line Bismark Meadows Dr 5.6 W from E line House 15.0 E from W line House 33.5 Main to property line 12.0 Pipe inside property 33.5 C. Smith & Son installed new service. Percy Reynolds | | | | |

| METER HISTORY | | | | | | | CHARGE OUTS | | | |
|---------------|-----|------|-------------------|--------|--|-----|-------------|---|---------|-----|
| DATE | SET | SIZE | MAKE | NUMBER | READING | | TEST | | REMARKS | |
| | 001 | | | | | | | | | 457 |
| | | | with the state of | 4 | (a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c | | | | | |
| | | | 11_ | | | | | - | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | Y | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | 8 8 | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | - | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | 1 1 | 1 | | | | | 1 | | | |