

P 106 L 101

APPLICATION No.: 33616

LOCATION:

132 Whitman St (formerly service # 9922)  
killed

OWNER:

Paul &amp; Susanne DaSilva

Contractor: Nelson Cardoso

31-313

MEASURES:

3/4"

Copper

04-21-2010

E from E line No. Front St	114.6
N from S line Whitman St	7.3
W from E line House	12.3
E from W line House	13.0
N from N line House	17.0
Main to Property Line	14.0
Pipe inside Property	12.0

## TAP CLEARED

DATE

BEF.

AFT.

REMARKS

NOTE: New tap is 1 ft W x old tap (#9922)  
4/21/10 - Inspected by Percy Reynolds  
-----

[illegible]



# Service killed at Tap

APPLICATION No.: 9922

TAP CLEARED

LOCATION: 132 Whitman

OWNER: Jos Rezendes

MEASURES: 5/8"

E from	Front	114.6 ft.
N from S	Whitman	9.0 ft.
W from E	house	12.3 ft.

4/21/2010 - Nelson Cardoso killed this service at the tap.  
 Installed a new service to this house - Tap is  
 1' West of this tap. See Service # 33616  
 Inspected by Percy.

DATE

BEF.

AFT.

REMARKS



[illegible]

## CHARGE OUTS

[illegible]