

33703

LOCATION:

OWNER:

**MEASURES:**

Contractor: RJ Canessa

1''

Copper

08-31-2011

W from W line Mt. Pleasant St

214.0

N from S line Jones St

7.0

W from E line House

## 5.4

E from W line House

29.0

N from N line House

36.2

## Main to Property Line

14.0

## Pipe inside Property

33.0

8/24/11 - RJ Canessa installed this service

Inspected by Percy Reynolds

-----

TAP CLEARED

BEF.

AFT.

REMARKS

[illegible]

[illegible]

## CHARGE OUTS

[illegible]