| P 130 F L 19 33746 | | TAP CLEARED | | | | |
|--|------|-------------|------|---------|--|--|
| LOCATION: 9 Tarkiln Place | DATE | BEF. | AFT. | REMARKS | | |
| OWNER: Triple Horn LLC | | | | | | |
| MEASURES: Contractor: MHT Excavating | | | | | | |
| 6" Ductile Iron 09-25-2012 Fire Supply | | | | | | |
| S from S line Chaffee St 370.0 N from N line of Wall 19.2 | | | | | | |
| E from E line Building 4.0 N from N line Building 39.5 | | | | | | |
| Main ends 5 ft S x Hydrant Pipe inside Property 25.0 | | | | | | |
| New Hydrant is 92.5 ft S x existing Hydran | nt | | | | | |
| Hydrant is N x Wall 2.8 Hydrant Gate Valve is N x Wall 8.9 | | | | | | |
| 9/25/12 - MHT Excavating Laid 6" Fire Supply Inspected by Percy Reynolds | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

| METER HISTORY | | | | | | | | CHARGE OUTS | | |
|---------------|-----|------|------|--------|---------|---|------|-------------|----------------------|--|
| DATE | SET | SIZE | MAKE | NUMBER | READING | | TEST | | REMARKS | |
| | 001 | | | | | | | | | |
| | | | | | | | | | W Security Statement | the state of the s |
| | | | | | | | | | * 1 200 | and the state of t |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | - | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | - 3 | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |