| 711 | APPLICATION No.: 33972 | TAP CLEARED | | | | |
|--------------|--|-------------|------|------|---------|--|
| LOCATION: HO | APPLICATION No.: 339/2 Iden St NS 280' E x Felton St | DATE | BEF. | AFT. | REMARKS | |
| OWNER: | | | | | | |
| MEASURES: | | | | | | |
| | 1" COPPER ASservice | | | | | |
| | P.118 L.223 FECTON ST. E x E Line 285.0' S x N Line Holden St 13.0' W x E Line House 21.7' E x W Line Garage 35.0' S x S Line House 31.3' Main to property line 33.6' | | | | | |
| | Pipw inside property 21,0' | | | | | |
| | 2-26-18: Contractor RJ Canessa installed new copper service; Inspector P. Reynolds | SX | | | | |
| | , Energiolds | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

| METER HISTORY | | | | | | | CHARGE OUTS | | | |
|---------------|-----|------|------|--------|---------|---|-------------|------|---------|--|
| DATE | SET | SIZE | MAKE | NUMBER | READING | | TEST | | REMARKS | |
| | 001 | | , | | | | | | | |
| | | | | | | - | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | 1357 | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| - | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | 1 | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |