

34117

APPLICATION No.:

LOCATION: WS Lambeth St N x Tarklin Hill Rd

TAP CLEARED

DATE

BEF.

AFT.

REMARKS

OWNER:

31-313

MEASURES:

P125A L.490

Right side of Duplex (to be converted to a condo)

Sewer#24918 -- Left side water service#34118

N x N Line Tarklin Hill Rd 724.5'

N x Hydrant #5-0488 63.3'

E x W Line x Lambeth St 18.0'

S x N Line x Building 34.5'

N x S Line x building 38.0'

E x E Line x building 38.0'

E x W Line x Lambeth St 40.0'

Pipe inside property 21.0'

Main to curb stop 22.0'

5-11-2021: RJ CANESSA INSTALLED NEW SERVICE  
INSPECTOR: MANUEL ROSE

[illegible]

## CHARGE OUTS

[illegible]



APPLICATION No.: 34117

LOCATION: WS Lambeth St N x Tarkiln Hill Rd

OWNER:

31-313

MEASURES: plot 125a lot 490 right side of duplex to be  
converted to a condo down the line  
5.18.2021 cont. into the Bldg.  
Contr. RJ Canessa Inspect. Percy  
sewer #24918--left side water # 34118  
1" copper

N x n line Tarkiln Hill	732'
N x hydrant	63'
E x W line Lambeth	18'
S x N line house	32'
N x S line house	38;
E x E line house	37'
main to prop. line	42'
pipe inside prop.	23'

## TAP CLEARED

DATE \_\_\_\_\_

BEF.

AFT.

REMARKS

[illegible]

## CHARGE OUTS

[illegible]