

78

APPLICATION No.: 23647

TAP CLEARED

LOCATION: 36 Linden

OWNER: Bertha Pendleton

MEASURES:

5/8"

W from

N from S line

W from E line

Pleasant

Linden

house

136.9ft.

5.3 ft.

1.7 ft.

March 29, 1976 Renewed from the main to inside cellar.
 25 ft. - 3/4" Copper tubing 3/4" Curb Stop
 Tap Reamed 5/8" x 3/4" Fig. 413
 Stop Box

- - -

August 3, 1994 Pitta - found lead coming into cellar wall with
 compression fitting. Unknown where copper went to?
 Owner notified - must change to copper - was shut off since 1991

8/19/94: Nelson Cardoso Cont. renewed service from property line
 to ins. cellar (12ft ins.prop line) Cont. supplied all stock
 & will maintain trench. Stock: 12ft 3/4" copper tubing
 1-3/4x3/4 cop-cop cplg comp. ===== Insp. J Garcia

3/8/2012 - meter Blank 3/4 25.00

DATE

BEF.

AFT.

REMARKS

3/29/76

Reamed

[illegible]

78

APPLICATION No.: 9337

TAP CLEARED

LOCATION: Rear 36 LINDEN STOWNER: T. Richard

DATE

BEF.

AFT.

REMARKS

3/26/76

Reamed

MEASURES: $5/8"$

W from

Pleasant

125.3 ft.

N from S line

Linden

6.8 ft.

W from E line

house

4.5 ft.

March 26, 1976 Renewed from main to the prop. line.

16 ft. - $3/4"$ Copper tubing $3/4"$ Curb StopStop Box $5/8" \times 3/4"$ Fig. 413 $5/8" \times 3/4"$ lead connector

- - -

INACTIVE SER

[illegible]

CHARGE OUTS

[illegible]