| | | APPLICATION No.: 4919 | | TAP CLEARED | | | |
|---|-------------------|-----------------------|------------|-------------|------|------|---------|
| LOCATION:_ | 165 Grinnel | St. | | DATE | BEF. | AFT. | REMARKS |
| OWNER: Joao Galinho | | | | | | | |
| MEASURES: | 3/4" | Copper | Jan.9,1885 | | | | |
| | E from | Crapo St. | 116.8 ft. | | | | - |
| | S from N line | Grinnell St. | 6.7 ft. | | | | |
| | E from E line | house | 1.4 ft. | | | | |
| April 2, 1951 Renewed from Main to property line 26 ft. of 3/4" copper tubing 3/4" curb stop Fig. 415 3/4" copper x I. P. Coup. Female Fig. 413 | | | | | | | |
| April 11, 1961 Repaired a copper service by installing a Dresser coupling 2½-ft. outside curb stop 3/4" Dresser Cplg., Caldwell stop bos, complete | | | | | | | |
| 1" Copper Service 09/14/2018 Lead Service Line Replacement Program Phase 1, Contractor P Gioioso & Son Type CU, Diameter 1in, Water pressure 100 Distance from main to curb stop (ft) N/A Distance from curb stop to meter (ft) 37 Distance from curb face to curb stop (ft) 2 Depth of service (ft) 3.5 Total length of new pipe installed (ft) 31 Curb stop replaced: no Corporation replaced: no | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | - | |
| | avle furnished: y | | | | | | |
| BRADBURY-WARING, INC. | | | | | | | |

