

APPLICATION No.: 5502

TAP CLEARED

LOCATION: 208 Rockland St

OWNER:

31-313

MEASURES: 1" Copper Service

10/12/2018 Lead Service Replacement Program

Phase 1, Contractor P Gioioso & Son

Type CU, Diameter 1in, Water pressure 90

Distance from main to curb stop (ft) N/A

Distance from curb stop to meter (ft) 28

Distance from curb face to curb stop (ft) 1

Depth of service (ft) 5

Total length of new pipe installed (ft) 28

Curb stop replaced: No Corporation replaced: No

Ball valve replaced: Yes size 1"

DATE

BEF.


AFT.

REMARKS

[illegible]

CHARGE 0010

APPLICATION No.: 5502

TAP CLEARED 

LOCATION: 208 Rockland St.

OWNER: Deolinda Perry

MEASURES: ~~3/4"~~ ~~5/8"~~ ~~LEAD~~ ~~Copper~~ ^{now all} _{Copper} May 11, 1887

W from Lombard St. 53.0 ft.

N from S line Rockland St. 6.8 ft.

W from E line house 2.2 ft.

 April 3, 1964 Renewed service from 6" outside curb stop to property line.

7 1/2 ft. of 3/4" copper tubing 1 3/4" cop. to cop. stop
 2 lbs. wiping solder

11/3/11 - New measures

W from W line Lombard St	54.8
N from S line Rockland St	6.8
W from E line House	4.0
E from W line House	19.0
N from N line House	10.4
Main to Property line	14.0
Pipe inside property	5.0

11/3/11 - RJ Canessa renewed this service from the main to the meter. Owner charged \$115 (\$70 inspection fee & \$45 turn-on

Note: Tap is W x Lombard St 54.0
 Inspected by Percy Reynolds

[illegible]

CHARGE OUTS

[illegible]