

APPLICATION No.: 5876

TAP CLEARED



LOCATION: 574 So. Second St.

OWNER: Marv F. Barabe

MEASURES:

1/2" H lead Sept. 12, 1888

S from Division St. 171.0 ft.

W from E line Second St. 6.3 ft.

N from S line house 11.4 ft.

4/4/89: Renewed from 1/2' outside curb stop to ins cellar
(9ft. ins. prop line) Stock: 16ft. 3/4" copper tubing
1 - 3/4" curb stop 1-Caldwell stop box 1-3/4x5/8 lead to
cop adapt. xs.

[illegible]

3/8/05 Renewed from main to inside cellar (6 ft ins drop line)
STOCK: 26 ft - 3/4" copper tubing; 1 - 3/4" curb stop; 1 Caldwell
stop box; 1 - 5/8 x 3/4 Fig 413

NOTE: Pulled service accidentally - had to renew inside cellar, also had to repair broken sewer...1 - 5 ft section 6" PVC;
2 - 6" clay to plastic Fernco cplgs

3/7/07 Repaired 2 - 6" sewer services off 6" tee. Stock:
6" x 6" x 6" tee; 6" x 22° bend; 10 ft. 6" PVC; 6" x 90° bend;
2 rubber cplgs. clay-PVC Bento

Year	1990	1991	1992	1993	1994	1995	1996
1990	1990	1991	1992	1993	1994	1995	1996

BRADBURY-WARING, INC.

[illegible]

CHARGE OUTS

[illegible]