| | APPLICATION | No.: 6411 | TAP CLEARED | | | | | |
|---|-------------------|----------------------|-------------|------|------------|---------|---|--|
| LOCATION: 421 Pleasant | | | DATE | BEF. | AFT. | REMARKS | V | |
| OWNER: A.P. Kirkwood | | | | | | | | |
| MEASURES: 5/8" | | | | | | | | |
| S from | School | 121.8 ft. | | | | | | |
| E from W line S from N line | Pleasant House | 6.4 ft. 13.0 ft. | | | | | | |
| December 11, 1964 Renewed serv | vice from 6" | outside curb stop to | | | | | | |
| 4 ft. inside curb stop. 4 ft. of 3/4 copper tubing | 7 3/111 000 | 2 to con aton | | | | | | |
| 2 lbs. wiping solder | 1 3/4 601 | p. w cop. scop | | | | | | |
| Oct. 26, 1979: Franklin renewed | | | | | | | | |
| 21 ft3/4" coppe (6 inside) 1-3/4" curb stop | | | | | | | | |
| 1-Caldwell stop box | | | | | | | | |
| 1-5/8" x 3/4" Fig. 413 | | | 9.19 | | | | | |
| | | | | | | | 7 | |
| | | | | | | | | |
| | | | | -37 | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | Min De Car | | | |
| | | | | | 7 | | | |

| METE | RH | IST | ORY | | | | | | CHARGE OUTS |
|--------|-----|------|-------------|------------------------------|---------|---|------|---------|-------------|
| DATE | SET | SIZE | MAKE | NUMBER | READING | - | TEST | REMARKS | |
| 6-5-67 | | 5/8 | Rockwell Ma | g 197 6 88 7 2 | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | 1 | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | 7.3 | | | | | | |