

APPLICATION No.: 6614

TAP CLEARED 8944-3840

LOCATION: 11 Margin St.

OWNER: James R. & Alice Cunha

DATE BEF. AFT. REMARKS

11/2/89: TAP REAMED

MEASURES: 1/2" H lead Oct. 22, 1890

N from Brock Ave. 94.7 ft.

E from W line Margin St. 6.6 ft.

N from S line House 9.9 ft.

11/2/89: Renewed from main to property line

Stock: 18 ft. 3/4" copper tubing 1-3/4" curb stop

1 - Caldwell stop box 1-3/4x5/8 lead to cop adapt. xs

1 - 3/4 x 5/8 Fig. 413

Aug. 21, 1989 Renewed from newly installed 6" ductile main to a point

9" Brito Const. supplied all stock:

9" of 3/4" copper tubing 1 - 3/4" corp. tap

1 - 5/8" x 3/4" lead to cop adapt XS

1" Copper Service

05/28/2019 Lead Service Replacement Program

Phase 1, Contractor P Gioioso & Son

Distance from main to curb stop (ft) N/A

Distance from curb stop to meter (ft) 16

Distance from curb face to curb stop (ft) 2.4

Depth of service (ft) 4

Total length of new pipe installed (ft) 16

Curb stop replaced: No Corporation Replaced: No

Ball valve replaced: yes size 1"

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS
5-11-67		5/8	Hersey	533233					

The diagram shows a rectangular structure with a semi-circular end. A vertical line segment on the right side of the rectangle is labeled "9' feet" and "meter". A horizontal line segment from the center of the arc to the right edge is labeled "16' feet". The arc is labeled "13' feet" and "16' feet".

