APPLICATION No.: 665		TAP CLEARED 851/-0015			
LOCATION: Rear 130 Summer	DATE	BEF.	AFT.	REMARKS	
OWNER: Rachel Dimock					
MEASURES: 5/8"					
S from Maxfield 93.8 ft.					
W from E line Summer 5.9 ft. N from N line - House 3.5 ft.					
5/21/85: Renewed from ½' outside curb stop to prop line					
Stock: 7ft.2" $3/4$ " copper tubing 1 $3/4$ " curb stop 1 Caldwell stop box $= \frac{1}{2} = 3/4 \times 5/8$ $\frac{1}{2} = \frac{3}{4} = 3/4 \times 5/8$					
1 Caldwell stop box $= \frac{1}{2} = 3/4 \times 5/8$ $\frac{1}{2} = \frac{3}{2} = \frac{1}{2} = 3/4 \times 5/8$					
12/09/04 - Silva Cont. #4 renewed service with 24 ft. copper					
Has leak in private property - sent letter		-			
11/9/09 Owner called will start repair end of this week - Will try to					
11/9/09 Owner called will start repair end of this week. Will try to replace service from prop. line to meter. Weston Lant 508-642-3497				<u></u>	
12/7/00 - Ormon reported convice from proceeds line to				<u> </u>	
12/7/09 - Owner renewed service from property line to meter - Owner charged \$185 (\$45 shut-off, \$70 Inspection				.4	
\$25 -3/4" meter couplings & \$45 turn-on. INspected by	<u></u>			**	
Percy Reynolds See New measures - 3/4" Copper					
S from S line Maxfield St 93.8 N from N line Hillman St 163.5					
W from e line Summer St 5.9					
S from S line 130 Summer St 4.5 (front house)					
W from W line House 99.9  Main to Property Line 26.0  Pipe inside Property 110.0					
110.0					
	1				

METER HISTORY										CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	
4-27-6	7	5/8	Hersey F	523215						
					- 1					
			FR							
	<i>(</i> -		FRant 130	130 REMR	×	1				
- J. Cimmer	-	-0-	3 is so with the sound of the s	4.		2	_			
_ , 4			, ω	3.5						
		1		128						
-										
_										
					W. Comments					
			4							