

APPLICATION No.: 6876

LOCATION: 52 Winsor St

TAP CLEARED

OWNER:

31-313

MEASURES: 1" Copper Service 7/11/2019
 Lead Service Line Replacement Program
 Phase 1, Contractor P Gioioso & Son
 Type CU, Diameter 1in, Water pressure 95
 Distance from main to curb stop (ft) 15
 Distance from curb stop to meter (ft) N/A
 Distance from curb face to curb stop (ft) 2
 Depth of service (ft) 3.5
 Total length of new pipe installed (ft) 15
 Curb stop replaced: Yes size 1"
 Corporation replaced: Yes size 1"
 Ball valve replaced: No

DATE

BEF.


AFT.

REMARKS

METER HISTORY

CHARGE OUTS

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS



APPLICATION No.: 6876

TAP CLEARED

LOCATION: 52 "insor

OWNER: Antony Rebello

MEASURES:

 $\frac{1}{2}$ " 5/8 H. LEAD

July 29, 1891

E from	Grape	448.6 ft.
N from S	Winsor	8.8 ft.
W from E	House	10.4 ft.

Ser increased to 3/4 Meter from curb Stop into Bldg.
8/9/62

Aug. 9, 1962 Renewed from $\frac{1}{2}$ ft. outside curb stop to meter inside
the building.
22 ft. of 3/4" copper tubing 1 3/4" cop. to cop. stop
1 lb. wiping solder

APR. 6, 1920 THIS SERVICE WAS REPLACED WITH 5/8 H. LEAD
USING 13 FT. OF PIPE

CITY - 19 FT. EARTH
18 FT. PIPE

TAKER - 13 1/2 H. LEAD

@ 424 = 5.67

LATER = 6.00

11.67

DATE

BEF.

AFT.

REMARKS



[illegible]

CHARGE OUTS.

[illegible]