| APP | PLICATION No.: 7016 | - | TAF | CLEAR | RED |
|---|--------------------------------|--------------------|------|-------|--|
| LOCATION: 378 Maxfield S.E. Cor. P. | | DATE | BEF. | AFT. | REMARKS |
| OWNER: Mary Sullivin | 1- | 1-17-01 Tap reamed | | | |
| | | | 1 | | |
| MEASURES: 5/8" S from | Maxfield 34.6 f | t. | | | |
| W from E line | Park 6.7 f | t. | \ | | |
| N from S line | House 3.8 f | t. | | | |
| May 5, 1977: Leak at curb stop. Repair 6" outside | e curb stop to property line. | | | | |
| 8 ft3/4" copper; 3/4" curb stop; 2. | -5/8" x 3/4" lead to copper | | | | |
| adapt. XXS; Caldwell stop box; | | | | | |
| 8/23/78: Renewed from curb stop 16 ft3/4" copper (8 ft. inside | to indide cellar wall. | | | | |
| 16 113/4 copper (0 11. 11131d | C , | | | | |
| 1-1701 Zenone Const. renewed from | | | | | |
| 25 ft 3/4" Copper tubing, 1 - 3 Box, 1 - 5/8" x 3/4" Fig. 413. Zen | 6/4" Curb Stop, 1 - Caldwell S | top | | | |
| 2011, 1 270 1 374 118. 413. 2011 | tone const. to maintain cut. | | | | |
| | | | | 2. | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | The state of the s |
| | | | | | |

| METE | RH | IST | ORY | | | | | | CHARGE OUTS |
|---------|-----|------|----------|--------|---------|------|---------|---------|--|
| DATE | SET | SIZE | MAKE | NUMBER | READING | TEST | | REMARKS | |
| 8-18-66 | | 5/8 | Hersey F | 533400 | | | U 4 9 Y | | and the second s |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | 7.0 | | | | | |
| | | | 11/6 | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | : | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | * 100 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | , | | |
| | | | | | | | | | |
| | | | | | | | | | |