

191 APPLICATION No.: 7078  $\frac{1}{2}$ " H lead  
LOCATION: ~~189-91-93~~ Belleville Ave.

OWNER: William Pennif

MEASURES:  $\frac{1}{2}$ "  $\frac{3}{4}$ " Meter H led Jan. 22, 1892  
N from Beetle ~~18.6 ft.~~ 18.4 ft.  
E from W line Belleville Ave. ~~8.8 ft.~~ 7.6 ft.  
N from S line House ~~18.8 ft.~~ 18.4 ft.  
Ser. increased to  $\frac{3}{4}$ " from Curb Stop into Bldg.  
E x E line House 9.6 ft.

January 2, 1963 Renewed from  $\frac{1}{2}$  ft. outside curb stop to meter inside cellar.

15 $\frac{1}{2}$  ft. -  $\frac{3}{4}$ " copper tubing; 1# wiping solder;  
1 -  $\frac{3}{4}$ " cop to cop stop, fig. 415;

Dec. 13, 1955 Repaired leak at tap.

1 ft. -  $\frac{3}{4}$ " copper tubing; 1- $\frac{3}{4}$ " cop to I.f. cplg, fig. 413; 1 wiped joint - tap reamed.

7/7/76-Due to the inst. of the new 48" main this service has been renewed from the main to 9 ft. from the main. Stock supplied & inst. by Zoppo. 1" corporation Ford Compression; 1" x  $\frac{3}{4}$ " Reducer; 9 ft.

$\frac{3}{4}$ " copper;  $\frac{3}{4}$ " curb stop ford Compression; Measures of 1" Corp.  
N x N line Beetle St. 19.6 ft. E x W line Belleville Ave. 18.0 ft.

TAP CLEARED

DATE BEF. AFT. REMARKS

✓

## METER HISTORY

## CHARGE OUTS

[illegible]

191 Belleville Ave APPLICATION No.: 7078

LOCATION:

OWNER:

31-313

MEASURES:

Lead service line replacement program phase 1  
8/20/2018:

Contractor: P.Gioioso & Sons.

Type: CU, Diameter 1, Water Pressure 80

Distance from main to curb stop 24.5'

Distance curb stop to meter 0

Distance from curb face to curb stop 2'

Depth of service 4'

Total length of new pipe installed 24.5'

Curb stop replaced YES: Size 1"

Corporation replaced YES: Size 1"

Ball Valve furnished NO:

TAP CLEARED

DATE

BEF.

AFT.

REMARKS

## METER HISTORY

## CHARGE OUTS

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS

