

APPLICATION No.: 7481

TAP CLEARED

LOCATION: 130 Rockland St

OWNER: _____

31-313

MEASURES: 1" Copper Service

10/29/2018 Lead Service Replacement Program

Phase 1, Contractor P Gioioso & Son

Type CU, Diameter 1in, Water pressure 90

Distance from main to curb stop (ft) N/A

Distance from curb stop to meter (ft) 21

Distance from curb face to curb stop (ft) 2.5

Depth of service (ft) 3.8

Total length of new pipe installed (ft) 21

Curb stop replaced: No

Corporation replaced: No

Ball Valve replaced: Yes size 1"

DATE

BEF.

AFT.

REMARKS

[illegible]

APPLICATION No.: 7481

TAP CLEARED 8802-0378

LOCATION: 130 (Bury) Rockland St.

OWNER: Mary L. Parr

MEASURES: $\frac{1}{2}$ " H lead Dec. 15, 1892

W from Bonney St. 156.6 ft.

N from S line Rockland St. 6.8 ft.

W from E line bay window 2.1 ft.

E from Orchard St. 26.7 ft.

1/11/88: REnewed from main to prop line. Stock: 16.0 ft. 3/4" copper tubing 1-3/4" curb stop 1-Caldwell stop box

1 - 3/4x5/8 lead to cop adapt. xs 1-3/4x5/8 Fig. 413

10/25/95 Pat from DPW notified us that owner
 Fernando Linkeiro had water going into cellar from
 hose draining into yard Problem was taken care of
 but might file complaint

[illegible]

CHARGE OUTS

[illegible]