

APPLICATION No.: 7526

TAP CLEARED

LOCATION: 124 & R. Bonney St.

OWNER: Manuel M. Costa

MEASURES: 5/8"

H lead

Mar. 30, 1893

N from

Rockland St.

208.2 ft.

W from E line

Bonney St.

7.4 ft.

N from S line

house

7.8 ft.

July 23, 1954 Renewed from main to property line

28 ft. of 3/4" copper tubing type K, soft

1-3/4" cop. to I.F. coplg. fig. 413

1-3/4" copper stop, fig 415

1 wiped joint - tap reamed

1 sidewalk cut: 4' x 2' Warrenite

2 street cuts: 4' x 2' ' 4' x 2' Warrenite

Marks

Cambra

5/13/2022: Inspection for cut + cap water/sewer. Water cut @ property line will reconnect at a later time. Contractor JLC Construction Inspector Manuel Rose, Contractor couldn't find sewer in sidewalk to much ledge sewer cut + plugged inside cellar in meter pit. (engineering/stephanie was made aware)

[illegible]

CHARGE OUTS