

APPLICATION No.: 7791

TAP CLEARED 8752-1912

LOCATION: 159 Hillman Taps Cedar

OWNER: Leonard R Yetyet

MEASURES:

3/4"

N from

Hillman

27.8 ft.

W from E line

Cedar

7.3 ft.

S from N line

House

20.5 ft.

DATE

BEF.

AFT.

REMARKS

8803-1515

1/21/88

tap reamed

4/31/86

960501690

CLEAR  
ELIC

Jan. 4, 1960 Renewed from  $\frac{1}{2}$ ' outside curb stop to 3' inside curb stop  
 $3\frac{1}{2}$ ' of 3/4" copper tubing 2lbs. wipign solder  
 3/4" cop. to cop. stop, fig. 415 ---

12/28/87: Renewed from 1 ft. outside curb stop to ins. cellar.  
 ( 2ft. ins. cellar) Stock: 8ft. 3/4" copper tubing  
 1 - 3/4" curb stop 1-Caldwell stop box 1 - 3/4x5/8 lead to  
 cop adapt. xxs. =====

*Poor pressure Tap has to be reamed.*

1-21-88 Renewed from main to curb stop: 21 ft 3/4" copper tubing  
 1-3/4x3/4 Fig 413

Jan 31, 1996:

poor pressure Disconnected and reamed tap  
 Stock: same Fig 413 =====

[illegible]

## CHARGE OUTS

[illegible]