	APPLICATION No.: 8452							
LOCATION: 124-126	124-126 Crapo St.						ARKS	
	Charles Catin						Reamed 1	
	H lead	Feb.14,1896	July 1	3,1995	: tap	reamed	V	
E from	Crapo St.	7.6 ft.		4 7				
N from S line	Katherine St.	9.2 ft.						
E from W line	house	6.2 ft.						
ADDITIONAL MEASURES: E x Crap	ide curb stop to a ping 1-3/4" curb st  x5/8 lead to cop ada  ST RECONSTRUCTION  ce from main to propil maintain trench bing 1-3/4" curb sop adapt.xs 1-3/4x5  SERV.IS OFF KATHERIN	oint 6½ ft. op pt. xs. line top /8 Fig 413						
BRADBURY-WARING, INC.								

METER HISTORY										CHARGE OUTS			
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS				
3/17/66		5/8	Rockwell Mag	19378392									
The same				4									
	-												
									7				
					410 14 15				*				
					1								
	1	- 1											

APPLICATION No.: 8452	TAP CLEARED			
LOCATION: 124-126 Crapo, S.E. Cor. Katherine	DATE	BEF.	AFT.	REMARKS
OWNER:				
OWNER:  MEASURES: 1				

METER HISTORY										CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	CHARGE OUTS
	OUT									
						-				
					San			1		
						-				
						-				
						-				
						-				
					S A					
		1				-				