APPLICATION No.: 8538 1 H lead TAP CLEARED LOCATION: 399 Belleville Ave. OWNER: Manuel A. Baptista MEASURES: 1 H lead May 5, 1896 W from Belleville Ave.(South) 24.1 ft. S from N line Coffin Ave. 8.1 ft. E from W line House 3.4 ft. Feb. 18, 1949 Repaired leak on pipe 3' from curb stop in street. No pipe used	/
OWNER: Manuel A. Baptista MEASURES: 1" H lead May 5, 1896 W from Belleville Ave.(South) 24.1 ft. S from N line Coffin Ave. 8.1 ft. E from W line House 3.4 ft. Feb. 18, 1949 Repaired leak on pipe 3' from curb stop in street. No pipe used	
MEASURES: 1" W from S from N line E from W line H lead May 5, 1896 W from S from N line House S of the House Feb. 18, 1949 Repaired leak on pipe 3' from curb stop in street. No pipe used	
S from N line Coffin Ave. E from W line House 3.4 ft. Feb. 18, 1949 Repaired leak on pipe 3' from curb stop in street. No pipe used	
Feb. 18, 1949 Repaired leak on pipe 3' from curb stop in street. No pipe used	
No pipe used	-
No pipe used	
D C 2070 D- 3.0	
Dec. 5, 1972 Renewed from main to inside cellar. 43 ft 3/4" Copper tubing (3 ft. inside)	
Caldwell Stop Box 3/4 x 3/4 Fig. 413	
Tap reamed	

METE	R H	ISTO	DRY	CHARGE OUTS				
DATE	SET	SIZE	MAKE	NUMBER	READING	TEST	REMARKS	
					(1)			
				1				
			-					
					1			
					1			