158

APPLICATION No.: 8541 3/4

LOCATION: 160 Cedar St.

OWNER: I.C. Dade 1/1/1896

MEASURES: 3/4" Copper

E from	Cedar	42.1 ft.
N from S line	Maxfield	7.0 ft.
W from E line	House	4.7 ft.

Nov. 16, 1955 Repaired leak at tap.
1 ft. - 3/4" copper tubing; 1-1" x 3/4" cop to i.f. cplg.
Tap reamed; 1 wiped joint

- - -

Dec. 15, 1969 Renewed from 6" outside curb stop to the property line.
8½ ft. - 3/4" copper tubing; 1 - 3/4" Hays curb stop;
2# wiping solder;

- - -

10/15/90: Renewed from main to inside cellar (8ft. ins prop line) Stock: 23ft. 3/4" copper tubing
1- 3/4" curb stop 1-Caldwell stop box 1-3/4x3/4 Fig.413

Jan. 1, 1991 shut off at curb - water pipes broken in house -
Jan. 10, 1991 checked - off
11-4-91 checked Hansen - still off
11/6/91 meter missing

12/15/04 - Silva Cont. #4 renewed service with 26 feet copper

TAP CLEARED 2-23-6

DATE	BEF.	AFT.	REMARKS
			9042-0061
10/15/90: TAP REAMED			

METER HISTORY

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS

CHAR