

APPLICATION No.: 8647

TAP CLEARED

LOCATION: 220 Palmer

DATE

BEF.

AFT.

REMARKS

OWNER: Helen M. Bonayne

6/25/92 9226 4397

MEASURES:

3/4"

S from

Court

74.8 ft.

W from E line

Palmer

8.8 ft.

S from N line

House

3.5 ft.

6/25/92: TAP REAMED

11/20/96 Tap Reamed

January 2, 1968 Renewed from $\frac{1}{2}$ ft. outside curb stop to a point $2\frac{1}{2}$ ft. inside curb stop.

3 ft. $\frac{3}{4}$ " copper tubing used. Total 1 $\frac{3}{4}$ " curb stop. Mueller 2 wiped joints 1 Buffalo stop box.

Completely long bottom. Old stop box broken and pieces returned to the repair shop for scrap.

6/25/92: Renewed from main to a point 2ft Stock: 2ft $\frac{3}{4}$ " copper tubing 1- $\frac{3}{4}$ x $\frac{3}{4}$ lead-cop adapt. xxxxx 1- $\frac{3}{4}$ x $\frac{3}{4}$ Fig. 413

11/20/96 M. Pavao Const. renewed from main to property line. All stock supplied & installed by Contractor. 31 ft. - $\frac{3}{4}$ " Copper tubing, 1 - $\frac{3}{4}$ " Curb Stop, 1 - Caldwell Stop Box, 1 - $\frac{3}{4}$ " x $\frac{3}{4}$ " lead to cop. adapt. XX, 1 - $\frac{3}{4}$ " x $\frac{3}{4}$ " Fig. 413, M. Pavao to maintain cut.

4/12/19: Service renewed from curb stop to meter, JLC Construction P. Reynolds Inspected

N x S Line House 3.5'

N x S Line House 20'

W x W Line House 16.0'

Main to property line 30'

[illegible]

CHARGE OUTS

[illegible]