

APPLICATION No.: 9023

TAP CLEARED



LOCATION: 106 So. Seventh St.

OWNER: John A. Birknes

MEASURES: 5/8"

N from line Bedford 141.2 ft.
 W from E line Seventh St. 5.0 ft.
 N from S line #108 7.4 ft.

 August 7, 1963 Renewed from $\frac{1}{2}$ ft. outside curb stop to $\frac{1}{2}$ ft.
 inside the curb stop

1 ft. of $\frac{3}{4}$ " copper tubing 1 $\frac{3}{4}$ " cop. to cop. stop
 2 lbs. wiping solder

 January 4, 1950 1 $1\frac{1}{2}$ " cop. x $1\frac{1}{2}$ " cop. x $\frac{3}{4}$ " cop. tee A-1640
 1 $\frac{3}{4}$ " fitting to $\frac{3}{4}$ " I.P. fem. coupling A-1525
 1 $\frac{5}{8}$ " corporation fig. 226

 6/25/79: Renewed from 6" outside curb stop to a point
 6 ft. North from curb stop. 7 ft. $\frac{3}{4}$ " copper; $\frac{3}{4}$ " curb
 stop; Caldwell stop box; 2- $\frac{5}{8}$ " x $\frac{3}{4}$ " lead-cop. adapt. XS

OCT 3 1979: Franklin renewed service from the main to the
 prop. line.

45 ft. $\frac{3}{4}$ " copper
 1- $\frac{3}{4}$ " curb stop
 1-Caldwell stop box
 1- $\frac{5}{8}$ " x $\frac{3}{4}$ " ^{curb stop} fig. 413

1- $\frac{5}{8}$ " x $\frac{3}{4}$ " lead-cop. adapt.

July 10, 1992 J.S. Luiz Cont. damaged copper while digging around prop. line.
 Renewed from a point 8 ft. south of prop. line to cellar by J.S. Luiz Cont.

3/4" Copper tubing - 2 - $\frac{3}{4}$ " x $\frac{3}{4}$ " cop to cop
 Plgs, comp.

OVER

[illegible]

CHARGE OUTS

7-12-44	5/8	Hersey D.	522743
---------	-----	-----------	--------

Note: 2 - cop to cop cplgs, comp. are 4.0 ft. & 8.0 ft. \$ x Property line.