Service Killed APPLICATION No.: 9776	TAP CLEARED				
LOCATION: 469 So. Second	DATE	BEF.	AFT.	REMARKS	
OWNER:					
MEASURES: 2" Copper Tubing 11-24-33					
N from Blackmer 113.4 ft. E from W line SEcond 10.6 ft.	,				
N from S line Schoolhouse 57.0 ft.					
danta u Samuel Maria					
6/27/2011 Service Killed at Main					
by JB Lanagan Inspected by Percy					
,					
				-	
	1.				

METER HISTORY										CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING	TEST			REMARKS	
	001									
2-24-60		2 **	Cadmet	1661668		-				
2 21 00		~	Od Sillo	200200						
						7		-		
15						-				
						-				
-										
	400									
-						-				
	15									
						-				
										*
						-				
-										
					11.7					
						1				