Service Kilked at Tap APPLICATION No.: 9922	TAP CLEARED				
LOCATION: 132 Whitman	DATE	BEF.	AFT.	REMARKS V	
OWNER: Jos Rezendes		* _			
MEASURES: 5/8*					
E from Front 114.6 ft. N from S Whitman 9.0 ft.					
W from E house 12.3 ft.					
4/21/2010 - Nelson Cardoro Killed this service at the tap.					
Installed a new service to this house - Tap is					
1' West of this tap. See Service # 33616		-			
Inspected by Percy.					
				**	

METER HISTORY								CHARGE OUTS	P		
DATE SET SI		SIZE	MAKE	NUMBER	READING	TEST			REMARKS		
	001										10
5/15/62		5/8	Calmet	1764660							•)
-	-	-			-	-	-				
	_						-				
		_									
							-				
	$\neg \uparrow$	_									
							-				
								-			
	-	-									
	-	-					-				
	-										
		4	distribution of the second	and the second second							
1	1				1	1					