

N
DRAIN

Permit

No. 1021-1892

Blackburn St.

Cedar Grove north.

Repair Drain, Blackburn St. May. 28, 1892, at 3 P.M. by
John Holland.

From property of

Cook & Smith.

Located

Blackburn St. S. W. of Cedar Grove.

Account

Misc Ledger 324, 1892



Cedar

160⁰⁰

<

>1

↘ ↗

14⁰⁰

Blackburn St.



Grove St.