

DRAIN

Permit

No. 10768-20

Hillman

Cedar to Ash

enters Hillman St. Sewer

6" pipe

May 10, 1920.

From Property of


N. B. Roofing Co.

Located

n. s. Hillman St.

Account Misc. Ledger

Rock St.



Hillman St.