

DRAIN

Permit

No. 12823-23

Milford St.
Irvington - Carlisle
enters Milford St. Sewer

6" x 4" pipe


Dec. 4, 1923

From Property of

Richard Delude

Located W. S.

Account Misc. Ledger



Carlisle St

Milford St.

MH



110°

58°