

DRAIN

#319

BELLEVILLE AVE.

Permit

(U.S.) 40' (41") N. / Nye St.

No. 23118-2001

Enters

BELLEVILLE AVE.

Drain Plot No.

129

From Property of

BARRY DEMELLO

Inspected by Peter Scieszka on 8/7/01 from
prop. line to house. Used stub from demod.
building (#319). All cast iron was used for
service. Storm drain inspected by Joseph Martin
on 8/28/01.

P. 99
L. 159

S.D. inspected
by Joe Martin
on 8/28/01 - see
Bellville Ave.
Recor. - Ch. 90
plans and see
plan attached to permit.

