

Drainage

Permit: 24980/2021 #68




Address: Gisele's Way

Enters: Gisele's Way










Drain Plot: 199B

Plot/Lot: 134/314

From Property of: Stacy Oliveira


-  NBGIS DBO sManhole
-  NBGIS DBO swManhole
-  NBGIS DBO CommonManholes

Cleanout Type

-  Cleanout
-  Flushing Structure
-  Other
-  NBGIS DBO swCatchBasin
-  NBGIS DBO slateralLine
-  NBGIS DBO swGravityMain
-  NBGIS DBO sGravityMain
-  NBGIS DBO Interceptor
-  NBGIS DBO sPressurizedMain

Type

-  Oil Separator
-  Recharge



1 in = 50 ft