

✓
DRAIN

Permit

No. 852-1892

Durfee St.
Bullock to Shawmut.

Repair Drain. Durfee St.
February 24, 1892. at 8 A.M. by John
Holland.

From property of

Martha Turner.

Located

Durfee St. s. s. w. of Bullock.

Account

Misc. Ledger 112

Durfee St.

< 580 >

211 ⁰⁰

Bullock St.