

✓
DRAIN

Chestnut St.

Smith to Campbell.

Permit

No. 918-1892.

Repair Drain. Chest-
nut St. Apr. 6, 1892, at 3 P.M. by
John Holland.

From property of

Wm. J. Norton.

Located

Chestnut. w.s.w. of Smith.

Account

Misc. Ledger 196

Smith

Chestnut

Street.

