

N
✓
DRAIN

Permit

No. 977-1892.

Blackburn St.
Cedar Grove St north.

Repair Drain Blackburn
St. May 9, 1892. at 9 AM. by John Hol-
land.

From property of

Cook & Smith.

Located

Blackburn. w. s. n. of Cedar Grove.

Account

Miss. Lodge 282

Cedar



Grove. St.

135-

128

4²⁰
6
5¹¹
6

Blackburn.